

APR 29 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-24302
Property Name North Vacuum ABO North Unit	Well No. #001

7. Surface Location

UL - Lot L	Section 1	Township 17S	Range 34E	Feet from 1980	N/S Line South	Feet From 860	E/W Line West	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING IND A	DATE 04-17-2013
------------------	---------	--------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0		0	450	3300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Production casing had 450 psi. Bled off 1/2 bbl KCl. H2O had a drip after blowing down.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: <i>Trish Mealand</i>	ELG/OCD 4-29-2013
Printed name: Trish Mealand	OIL CONSERVATION DIVISION
Title: Production Analyst	Entered into RBDMS
E-mail Address: pmealand@limerockresources.com	Re-test
Date: 04-23-2013	
Phone: 575-623-8424	
Witness:	

MAY 06 2013