

MAY 14 2013

RECEIVED

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name John H. Hendrix Corporation	API Number 3002523609
Property Name Danglade	Well No. 002

7. Surface Location

UL - Lot A	Section 24	Township 22S	Range 37E	Feet from 330	N/S Line N	Feet From 990	E/W Line E	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status Active	SHUT-IN	PRODUCING P	DATE 04/17/13
-----------------------	---------	----------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0			16	16
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / (N)	Y / N	Y / N	Y / N	Y / N
Surges	Y / (N)	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / (N)	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / (N)	Y / N	Y / N	Y / N	Y / N
Water	Y / (N)	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:
None

Tracy A. Cobbs

Signature: <i>Carolyn Doran Haynes</i>	OIL CONSERVATION DIVISION Entered into RBDMS Re-test Date: 4/17/13 Phone: 432-684-6631 Tested by Allon Dobbs Witness:
Printed name: Carolyn Doran Haynes	
Title: Engineer	
E-mail Address: cdoranhaynes@jhhc.org	
Date: 4/17/13	

ELG/OCD 5-14-2013

MAY 22 2013