# New Mexico Off Conservation Division, District I

Form 3160-5 (March 2012)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

1625 N. French Drive Hobbs, PM 83240

FORM APPROVED OMB No. 1004-0137
Evnires: October 31, 2014

Expires. October 51, 201
5. Lease Sofial No. 062486
6. If Indian, Allottee or Tribe Name

SUNDRY	NOTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
abandoned well.	Use Form 3160-3 (APD) for such proposals

	orm for proposals t Use Form 3160-3 (A					
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas W	ell Other		Drick		and Unit #833	
2. Name of Operator Celero Energy II, LP				9. API Well No. 30-005-00994		
3a. Address		3b. Phone No. (include are	a code) 10. Field	and Pool or Explo	oratory Area	
400 W. Illinois, Ste. 1601 N		(432)686-1883		ock; Queen		
4. Location of Well (Footage, Sec., 7., (A) Sec 4, T14S, R31E 330' FNL & 990' FEL	R.,M., or Survey Description,  .			ly or Parish, State /es, NM		
12. CHEC	K THE APPROPRIATE BO	X(ES) TO INDICATE NAT	URE OF NOTICE, REPO	RT OR OTHER D	DATA	
TYPE OF SUBMISSION			TYPE OF ACTION			
Notice of Intent  X Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Statement of the Production (Stat		Water Shut-Off Well Integrity Other Response to Written Order	
Final Abandonment Notice	Convert to Injection	Plug Back	■ Water Disposal			
	Abandonment Notices must be final inspection.) Well Agreed Complia I have attached copy of the sundry to TA  OCD Complement Notices must be final inspection.)  OCD Complement Notices must be final inspection.  OCD Complement Notices must be final inspection.	ne filed only after all require ance Order #259 with pies of both agreement this well that was aptiance Orders do NOT meet for the pred for Record 05/23/2013. The large of the large of the pred for Record 05/23/2013. The large of the large of the pred for the large of the large	ments, including reclamation the OCD. Also, it is ents.  proved on 3/29/13 by the deral regulatory requirements well being brought into	on, have been comes on our 201.  y David Glas	pleted and the operator has  2 Plan of	
	ids And Minerals					
Lisa Hunt	ue and correct. Name (Frime)		gulatory Analyst			
Signature Lua	Hunt	Date 05/1	15/2013			
	THIS SPACE	FOR FEDERAL OR	STATE OFFICE US			
Approved by						
Conditions of approval, if any, are attached hat the applicant holds legal or equitable to entitle the applicant to conduct operations to Title 18 U.S.C. Section 1001 and Title 43	tle to those rights in the subject thereon.	t lease which would Office		FIELD OFFI		
Carrier on Catalland Comment	- 7/17		•			

(Instructions on page 2)

Form 3160-5 (March 2012)

#### UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 er 31, 2014

	Expires: Octobe
. Lease Serial No.	2486

SUNDRY NOTICES AND REPORTS ON WELLS

6. If Indian, Allottee or Tribe Name

	orm for proposais to Use Form 3160-3 (AF					
SUBMI	T IN TRIPLICATE – Other i	nstructions on page 2.	7. If Unit o	f CA/Agreement, Name and/	or No.	
1. Type of Well						
X Oil Well Gas W	Vell Other			y Queen Sand Unit#	833	
2. Name of Operator Celero Energy II, LP			9. API Wel 30-005	l No. 5-00994		
3a. Address	[3	Bb. Phone No. (include ar		nd Pool or Exploratory Area		
400 W. Illinois, Ste. 1601 N	Aidland TX 79701	(432)686-1883	Capro	Caprock; Queen		
4. Location of Well (Footage, Sec., T., (A) Sec 4, T14S, R31E			11. County	11. County or Parish, State		
330 FNL & 990 FEL			Chave	s, NM		
12. CHEC	CK THE APPROPRIATE BOX	K(ES) TO INDÍCATE NA	TURE OF NOTICE, REPORT	FOR OTHER DATA		
TYPE OF SUBMISSION			TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production (Start/	Resume) Water Shu	ıt-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Well Integ	grity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other	et	
Succequent repert	Change Plans	Plug and Abandon	n X Temporarily Aban	idon		
Final Abandonment Notice	Convert to Injection	· Plug Back	Water Disposal			
the proposal is to deepen directions. Attach the Bond under which the w following completion of the involve testing has been completed. Final determined that the site is ready for Celero would like to request RQU to the NNE be expanded to the NNE be expanded. The site is ready for the NNE works. The second of the NNE works. Th	vork will be performed or provided operations. If the operation Abandonment Notices must be final inspection.) St. TA status for 1 yr. Tided to include the DQ kstring.  '.'  102'. Load csg. t. 25 sx class C on CIEV. POOH LD workstring.  Field Office At Least. 24 How Mechanical Integrity Test. St. County, During Office How 27-0205. Engineer On Call 627-0275 Or Phone (After	orde the Bond No. on file was results in a multiple come filed only after all require. This well has utility a SU. Rig will be mostly after the sum of the	with BLM/BIA. Required subpletion or recompletion in a nements, including reclamation as a future WAGIW shall be subjected in the ving into the field the ving at surface.	sequent reports must be filed ew interval, a Form 3160-4 m, have been completed and the nould the CO2 project week of 3/25/13.	1 within 30 days must be filed once he operator has	
14. I hereby certify that the foregoing is to Lisa Hunt	rue and correct. Name (Printed)		gulatory Analyst		•	
LISATIUIL		line Re	guiatory Arialyst			
Signature Lua S	Hund	Date 03/	18/2013			
·	THIS SPACE F	OR FEDERAL OR	STATE OFFICE USE	⊒ - - Pa		
Approved by Danid R. L.	Mass	Title	PETROLEUM ENGINES	Date MAR	2 9 2013	
unditions of approval, if any, are attached not the applicant holds legal or equitable to notife the applicant to conduct operations to	tle to those rights in the subject		c ROSWELL.FE	BLD OFFICE		

#### BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)