

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 31 2013

BRADENHEAD TEST REPORT

RECEIVED

APR 2013

30-025-34038

Operator Name
Chevron U.S.A. INC.

Property Name
Haver 27

Well No.

3

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	Section	Feet from	E/W Line	County
F	27	17S	3SE	2091	FNL	1902	FWL	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
A		Pumping	10/21/2013

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1)-Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0 PSI	0 PSI		35	250
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(conductor 45) gas 11/13

ELG/000 10-30-2013

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: jhobbs@chevron.com	
Date: 10/21/2013	Phone: 575-631-4228
Witness:	

NOV 04 2013