2014		
Submit One Copy To Appropriate Diffice  State of New Me Office  Figure 4.	exico	Form C-103
Office District I  District II  OH. CONSERNATION DIVISION		Revised November 3, 2011
District II		WELL API NO. 30-025-33920
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410		STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Mraument 12'State
1. Type of Well: Oil Well Gas Well Other		8. Well Number 1008
2. Name of Operator		9. OGRJD Number
Chevron Mid Continent U.S.A.		<u>4373</u>
<ul><li>3. Address of Operator</li><li>15 Smith Road Midland Texas. 79705</li></ul>		10. Pool name or Wildcat  MONUMENT ABO NOTTH
4. Well Location		
4. Well Location Unit Letter N: 419 feet from the 5 line and 1801 feet from the W line		
Section 12 Township 195 Range 36E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) $GL - 3728$		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON		
PULL OR ALTER CASING   MULTIPLE COMPL	CASING/CEMENT	JOB
OTHER:	│	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have, been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease; all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
11212		•
SIGNATURE Warm Treffices TITLE Che	evron Surface Rep	DATE 5-12-2014
TYPE OR PRINT NAME David Frederick E-MAIL:	djzg@chevron.com	PHONE: 903-707-4067
APPROVED BY: Mah Walter TITLE Compliance Officer DATE 5/19/2014 TO MAY 19 2014		
20 2011		
		MAY # 3 YOU