

MAY 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name DKD LLC	API Number 30-025-34197
Property Name WATSON 6	Well No. #1

7. Surface Location

UL - Lot N	Section 6	Township 16S	Range 36E	Feet from 2857	N/S Line S	Feet From 1417	E/W Line W	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 5/21/14	SWD ACTIVE
-------------	---------	-----------	------------------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0			0	VAC
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ☒ WTR, ☐ GAS, ☐ CO2

Tubing ON VAC

B8 5/23/2014

Signature: Danny R Watson	OIL CONSERVATION DIVISION
Printed name: DANNY R WATSON	Entered into RBDMS
Title: PRES.	Re-test
E-mail Address:	
Date: 5/21/14	Phone:
	Witness:

MAY 27 2014