

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

APR 3 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chvron	API Number 30-025-41344
Property Name CW	Well No. 181

Surface Location

UL - Lot L	Section 36	Township 17S	Range 34E	Feet from 1420	N/S Line S	Feet From 730	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR NO	PRODUCER OIL	DATE 4/1/15
------------------	----------------	----------------	-----------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ	ϕ	ϕ	ϕ	1665
Flow Characteristics					
Puff	Y/N	N	Y/N	N	CO2 X
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS -
Down to nothing	Y/N	N	Y/N	N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 4/8/2015

Signature: T. E. Chevron	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 4/1/15	Phone: 390-4449
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

MAY 04 2015

h