

HOBBS OCD

JUL 13 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON Midcontinent		API Number 30-025-03810
Property Name LOUGINGTON SAN ANTONIO		Well No. 47

* Surface Location									
UL - Lot K	Section 1	Township 17S	Range 36E		Feet from 1980	N/S Line W	Feet From 1980	E/W Line W	County LEA

Well Status									
TA'D WEL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL PRODUCER	GAS	DATE 6-24-15	

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0	0	0	1700
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies:

BS 7/28/2015

Signature: Orlando Mendoza	OIL CONSERVATION DIVISION
Printed name: Orlando Mendoza	Entered into RBLMS
Title: Pumper	Re-test
E-mail Address: um65@chevron.com	
Date: 6-24-15	Phone: 970 959 3254
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

JUL 31 2015

L