

JUL 27 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC				Well Number 30-025-40061			
Property Name ABO REEF NW MEXICO L NCT 4				Well Name NET 44			
Surface Location							
1-1/2" Tap D	2-1/2" Tap 7	3-1/2" Tap 10S	4-1/2" Tap 35E	Feet from 990	Vis Lbs N	Feet from 1200	Feet from W
County LEA							
Well Status							
YES	PAID WELL ☒	YES	SHUT-IN ☒	INJ ☒	SWD ☒	PRODUCER ☒	DATE 5/22/15

OBSERVED DATA

	(A)Surface	(B)Intermt1	(C)Intermt2	(D)Prod Casing	(E)Tubing
Pressure	4	N/A	N/A	30	150
Flow Characteristics					
Pull	☒ Y / ☒ N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / ☒ N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	☒ Y / ☒ N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	Injected for
Water	Y / ☒ N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/29/2015

Signature:	OIL CONSERVATION DIVISION
Printed name: Ruben Rodriguez	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: T7CL@chevron.com	
Date: 5-22-15	Phone: 505-513-5526

JUL 31 2015