## HOBBS OCD

# State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

MAR 07 2016

### RECEIVED

#### BRADENHEAD TEST REPORT API Number Operator Name 30-025-38002 Chevron , N.S.A. Inc Well No. Property Name 342 Central Vacuum Unit 7. Surface Location Section Township Feet from N/S Line Feet From E/W Line UL - Lot Range County 36 34 E 1186 Lea 175 82 N Well Status TA'D WELL SHUT-IN INJECTOR PRODUCER DATE 0 YES YES **SWD** OIL GAS 3 7-17-16

#### **OBSERVED DATA**

. /	
NIN	
An O	

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0	N/A	0	1820
Flow Characteristics			1//		
Puff	Y / 🗞	Y / 🗞	Y / N	Y/65	CO2 _X
Steady Flow	Y / 🔊	Y / 🔞	Y/N	Ø/ N	WTR_A
Surges	Y / 🔊	Y / 10	Y / N	Y / 🛇	Type of Fluid
Down to nothing	0/ N	Ø/ N	Y / N	<b>⊘</b> / N	Injected for
Gas or Oil	Y / Ø	Y / 🔊	Y / N	Y / 🐼	Waterflood if applies.
Water	Y / Ø	Y / 🔊	Y/N	Y/Ø	7

Remarks – Please sta	e for each string (A,B,C,D,E) pertinent information regarding	bleed down or continuous build up if applies.	
Check	Permited Pressure		

Printed name: Tanner DeHaan		OIL CONSERVATION DIVISION		
		Entered into RBDMS 2 3 -8-16		
Title: FSA		Re-test		
E-mail Address: TZYR@Chevron	.com			
Date: Z-17-16	Phone: 575-390-4449			
	Witness:			