HOBBS OCD

Submit One Copy To Appropriate District State of New Mexico Office DEC 0 8 20 Hergy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Grand Ave., Arter NC EVOD CONSERVATION DIVISION 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	Form C-103 Revised August 1, 2011 WELL API NO. 30 35-025-35556 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name State A A/C 1 8. Well Number (131)
1. Type of Well: Oil Well Image: Company 2. Name of Operator Merit Energy Company	9. OGRID Number 14591
3. Address of Operator 13727 Noel Rd. Suite 1200 Dallas, Texas 75240	10. Pool name or Wildcat Jalmat, Tansill, Yates, 7 Rivers
4. Well Location Unit Letter I : 1980 feet from the South line and 660 feet from the East line Section 9 Township 23S Range 36E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB PM	
OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All pits have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, OUARTER/OUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
 The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. 	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE	DATE/2/6/2016
TYPE OR PRINT NAME CHARIS FORES E-MAIL HARS. FORES For State Use Only ENERGY	<u>e ment</u> PHONE: <u>575 420 5</u> 586
SIGNATURE	OFFicer DATE 120/16

B