Submit One Copy To Appropriate District	State of New Mexico	Form C-103
Office District I		Davised Mexamber 2, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. 1 2017	STATE 🛛 FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	1220 South St. Francis Dr. 112017 Santa Fe, NM 87505EP 112017	<ul> <li>5. Indicate Type of Lease STATE FEE</li> <li>State Oil &amp; Gas Lease No.</li> <li>7. Lease Name or Unit Agreement Name</li> </ul>
87505 SUNDRY NOTICES	SAND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	TO DRILL OR TO DEEPEN OR PLUG BACK TO A	ARNOTT RAMSAY F
1. Type of Well: Oil Well 🛛 Gas	s Well 🗌 Other	8. Well Number 3
2. Name of Operator		9. OGRID Number
LEGACY RESERVES OPERATING LP         3. Address of Operator		240974     10. Pool name or Wildcat
PO BOX 10848, MIDLAND, TX 7970	)2	JUSTIS; GLORIETA (PRO GAS)
4. Well Location		
Unit Letter <u>B</u> : <u>660</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>EAST</u> line		
Section <u>36</u> Township <u>258</u> Range <u>37E</u> NMPM <u>County LEA</u> 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3050' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
PULL OR ALTER CASING		
OTHER:		ready for OCD inspection after P&A
<ul> <li>All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.</li> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> </ul>		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
<ul> <li>Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> <li>If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with</li> </ul>		
	aining well on lease, the battery and pit location(s 's pit permit and closure plan. All flow lines, pro-	
from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well		
location, except for utility's distribution infrastructure.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE JAMAA )-		COOPDINATOR DATE 00/06/2017
SIGNATURE Xallafma	TITLE COMPLIANCE C	COORDINATOR DATE 09/06/2017
TYPE OR PRINT NAME <u>LAURA P</u> For State Use Only	E-MAIL:lpina@legacy	p.com PHONE: <u>432-689-5273</u>
	AL Dro	14/ 1000
APPROVED BY: Machaeler Conditions of Approval (if any):	TITLE P.E.S.	DATE 10/10/2017

## Whitaker, Mark A, EMNRD

From: Sent: To: Cc: Subject: Attachments: Tiffany Hunt <thunt@legacylp.com> Thursday, October 5, 2017 2:05 PM Davidson, Melissa Whitaker, Mark A, EMNRD; Laura Pina RE: Arnott Ramsay F #3 30-025-11900 789DB43B.JPG

## Melissa,

The Arnott Ramsay F #3 was flowing behind the 68025-00 meter, but that well has been plugged. Please see the attached picture. I don't think there ever was a meter on this well, but there is a line that it is out there that went from the # 3 and it is not our line nor is it tied to anything we own so we believe it is ETC's. A blind flange needs to be installed on the downstream side since this line is no longer active. There is no meter to be removed at this time b/c we still have another well flowing behind that meter.

Thanks,

Tiffany Hunt Marketing Representative Legacy Reserves Operating, LP 432-685-2277 <u>thunt@legacylp.com</u> 303 West Wall Suite 1800 Midland, TX 79701



Melíssa Davídson Senior Contract Administrator

Energy Transfer Partners 8111 Westchester Drive, Suite 600 Dallas, TX 75225 (469) 646-1514 melissa.davidson@energytransfer.com