

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

Murchison

LEASE OR FACILITY NAME *Bettis 20 ST COM*

WELL # *3H* API# 30-*025* - *41437*

U.L. *0* SEC *20* T *24s* R *33E*

FOOTAGE *200* N ☒ *2460* ☒ W

IS A FLARE STACK PRESENT? ☒ YES NO

IS FLARE ACTIVE? YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES NO

AREA AROUND FLARE CLEARED? ☒ YES NO

ENVIRONMENTAL CONCERNS *Prod gas going to sales via
Compressor*

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES NO

COMMENTS *Combustor is being used on tank vapors*

INSPECTOR *Larry Kolman* DATE *1-23-18*