

HOBBS OCD

JAN 23 2018

RECEIVED

FLARE INSPECTION

Murchison
LEASE OR FACILITY NAME Mogi 9 ST Com

WELL # 11 H API# 30-025-41787

U.L. P SEC 9 T 24s R 33e

FOOTAGE ~~200~~ N 350 E W

IS A FLARE STACK PRESENT? YES NO

IS FLARE ACTIVE? YES NO

IS GAS TO FLARE METERED? YES NO

AREA AROUND FLARE CLEARED? YES NO

ENVIRONMENTAL CONCERNS Prod. gas is going to sales

IS VRU PRESENT? YES NO

IS VRU ACTIVE? YES NO

COMMENTS Combuster being used on tank vapors

INSPECTOR Gary Robinson DATE 1-23-18