

District I

1625 N. French Dr., Hobbs, NM 88249

Hobbs District Office

State of New Mexico

Ñúífkjih9876êçää L2 L. L* L& L L ♣ ¥

Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron U.S.A, INC	³ API Number 30025 32623
Property Name STATE A	Well No. #9

7. Surface Location

UL - Lot H	Section 31	Township 17S	Range 35E	Feet from 2310	N/S Line N	Feet From 510	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

Well Status TIA	SHUT-IN	PRODUCING	DATE 3-21-18
---------------------------	----------------	-----------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	0	N/A	0	NONE
Flow Characteristics					TA
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: JUSTIN WALL	Entered into RBDMS
Title: Field Specialist	Re-test XJ
E-mail Address: LY4K@Chevron.com	
Date: 5-1-18	
Phone: 575-709-6224	
Witness: Dan Kolman	