

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

OCT 09 2018

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CROSS TIMBERS		API Number 30-025-23696	
Property Name NVA		Well No. 156 H	

7. Surface Location

UL - Lot J	Section 23	Township 17S	Range 34E	Feet from 1893	N/S Line S	Feet From 1800	E/W Line E	County LCA
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D Well YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	SHUT-IN YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	INJECTOR INJ <input checked="" type="checkbox"/> SWD <input type="checkbox"/>	PRODUCER OIL <input type="checkbox"/> GAS <input type="checkbox"/>	DATE 10/9/18
---	--	--	---	------------------------

OBSERVED DATA

	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	4200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

Remarks: Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: al Feyin	OIL CONSERVATION DIVISION Entered into RBDMS Re-test [Signature]
Printed name:	
Title:	
E-mail Address:	
Date: 10/9/18	Phone:
Witness: [Signature]	