

Submit 1 Copy To Appropriate District
Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-27529
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name H T Mattern NCT C
8. Well Number: 15
9. OGRID Number 4323
10. Pool name or Wildcat Penrose, Skelly, Grayburg
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3486' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Chevron USA, Inc.

3. Address of Operator
6301 Deauville Blvd., Midland, TX 79706

4. Well Location
Unit Letter B: 660 feet from the NORTH line and 1980 feet from the EAST line
Section 18 Township 21S Range 37E, NMPM, County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3486' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>		OTHER: <input type="checkbox"/>	
OTHER: <input type="checkbox"/>			

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 8 5/8" 24# @ 1197': TOC @ surface; 5 1/2" 15.5# @ 6810': TOC @ surface

Chevron USA Inc completed abandonment of this well as follows:

11/08/2018: MIRU. Pressure test CSG to 540 PSI for 10 minutes – good. Performed bubble test surface CSG – good. RIH and tag @ 3614'. Mark Whitaker(NMOCDD) approved and waived witness of test and tag. M/P 36 BBLs MLF to fill space between plugs up T/ 1393'. Spot 45 SKS Class C, 1.33 YLD 14.8 PPG, F/ 3614' T/ 3169'.

11/09/2018: Pressure test CSG to 500 PSI for 10 minutes – good. Spot 45 SKS Class C, 1.33 YLD 14.8 PPG, F/ 2683' T/ 2239'. WOC. Tag TOC @ 2229'. Pull up T/ 1393'. Mark Whitaker(NMOCDD) approved super plug. Spot 150 SKS Class C, 1.33 YLD 14.8 PPG, F/ 1393' T/ surface. Good cement to surface. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE P&A Engineer, Attorney in fact DATE 12/10/18

Type or print name Howie Lucas E-mail address: howie.lucas@chevron.com PHONE: (832)-588-4044

For State Use Only

APPROVED BY: [Signature] TITLE P.E.S. DATE 12/10/2018

Conditions of Approval (if any):

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.
Restoration Due By _____