

FLARE INSPECTION

COG	
LEASE OR FACILITY NAME: FE	Z FEE
WELL#	
U.L D SEC 9 T 255	R 35E
FOOTAGE 480 NS	190 E (W)
IS A FLARE STACK PRESENT?	YES NO
IS FLARE ACTIVE?	YES NO
IS GAS TO FLARE METERED?	YES NO
AREA AROUND FLARE CLEARED?	YES NO
COMMENTS: <u>Cauld not see</u>	Meter on place line - not in
use - prod gas gaing	
IS VRU PRESENT?	YES NO
IS VRU ACTIVE?	YES NO
COMMENTS: Tank Vapous 9	sing to combuster.

INSPECTOR May Kolinson	DATE 1-7-19