



FLARE INSPECTION

Centennial Resources

LEASE OR FACILITY NAME: Tour Bus 23 ST

WELL # # 503 API # 30- 025 - 43934

U.L. C SEC 23 T 225 R 34E

FOOTAGE 201 MS 2185 E 100

IS A FLARE STACK PRESENT? ☒ YES ☐ NO

IS FLARE ACTIVE? YES ☒ NO

IS GAS TO FLARE METERED? ☒ YES ☐ NO

AREA AROUND FLARE CLEARED? ☒ YES ☐ NO

COMMENTS: Looks like prod. gas is re-injected

IS VRU PRESENT? YES ☒ NO

IS VRU ACTIVE? YES ☒ NO

COMMENTS: Tank vapors going to combustor

INSPECTOR Ray Johnson DATE 3-20-20