Form 9-331 (May 1963)

16.

UNIT SUBMIT IN TRIPLICA (Other instructions DEPA

Form approved. Budget Bureau No. 42-R1424.

LEASE	DESIGNATION	AND	SERIAL	N
LC	063427			

10. FIELD AND POOL, OR WILDCAT

R	TMENT	OF	THE	INTERIOR	verse side)	
	GFOLO	GIC	AL SUI	RVEY		

GEOLOGICAL SURVEY	LC 06342/		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAM		
1. OIL GAS WE'L X WELL OTHER	7. UNIT AGREEMENT NAME Rich Unit		
2. NAME OF OPERATOR Santa Fe Energy Company	8. FARM OR LEASE NAME		
3. ADDRESS OF OPERATOR One Security Dark 7200 I 40 Heat American Compared to the control of the	9. WELL NO.		

One Security Park, 7200 I-40 West, Amarilto TX 79106

LOCATION OF WELL (Report location clearly and in accordance with any state requirements.*

At surface West Sawyer (San Andres) 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 1980' FSL & 560' FWL Sec. 15. ELEVATIONS (Show whether prodiff, etc.) CO

U.S. GEOLOGICA, ETC.) KR. 2 Sec. 34-T9S-R37E 15. ELEVATIONS (Show whether PROBLEM ETC.) 12. COUNTY S. GEOVERN KB 3996'

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 12. COUNTY OR PARISH 13. STATE 14. PERMIT NO. Lea MI

NOTICE OF INTENTION TO:				SUBSEQUENT METORICS.				
				1	1		1	
TEST WATER SHUT-OFF		PULL OR ALTER CASING			WATER SHUT-OFF		REPAIRING WELL	<u>_X</u>
FRACTURE TREAT		MULTIPLE COMPLETE			FRACTURE TREATMENT	l	ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*			SHOOTING OR ACIDIZING	XX	ABANDONMENT*	
REPAIR WELL		CHANGE PLANS			(Other)			
(Other)					(Note: Report res Completion or Reco	ults mple	of multiple completion on Well tion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1-2-80: thru

Pulled rods & pump. Found pull rod broken in pump. Found some scale on tbg. Ran bailer. Re-perforated 4978-5011' to loosen scale. Treated perfs with 1000 gal. 15% NEA. Returned to production. Squeezed w/

1-5-30:

scale inhibitor.

Test before: 3 BOPD & 23 BWPD Test After: 15 BOPD & 217 BWPD

8. I hereby certify that the bresoing is true and correct		Petroleum Engineer	DATE 2-1-80	-
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE	_

*See Instructions on Reverse Side