

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7097
7. Unit Agreement Name
8. Farm or Lease Name State "AE"
9. Well No. 4
10. Field and Pool, or Wildcat Wildcat
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole
2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1978, Roswell, New Mexico
4. Location of Well UNIT LETTER D 330 FEET FROM THE North LINE AND 990 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 8-S RANGE 36-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4074' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER _____ <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p>
---	--	--	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7-7/8" hole to 5006' T.D. without encountering commercial hydrocarbons. well was plugged and abandoned by setting the following neat cement plugs:

- 25 sx 4890-4990 (San Andres Porosity)
- 25 sx 4049-4149 (Top of San Andres)
- 25 sx 2768-2868 (Top of Yates)
- 25 sx 2269-2369 (Top of Salt)
- 25 sx 312-412 (8-5/8" casing)
- 10 sx in top of well.

Heavy SGOE mud was used to spot all plugs. 8-5/8" surface casing was left intact. A dry hole marker was erected. Well P & A 10/29/67.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed

SIGNED O. D. Bretches TITLE Dist. Drlg. Supervisor DATE 11-8-67

APPROVED BY John W. Ranzen TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: