



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **LC-000000**

Lease No. \_\_\_\_\_

MODS OFFICE OCC

1955 MAR 11 AM 11:29

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 26, 1955

Well No. **2-8** is located **1874** ft. from **[N]** line and **2384** ft. from **[E]** line of sec. \_\_\_\_\_  
**NE/4 of Section 8** **T-13-S, R-31-E** **S.14.7 N.**  
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**North Liberty, Texas** **Charles** **San Antonio**  
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 11" hole to 312'. Cemented 8-5/8" casing at 307.70' with 225 cu. ft. of cement. Will wait on cement 24 hours and test with 1000 psi.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Union Oil Company of California**

Address **619 West Texas Avenue**

**Midland, Texas**

By **James E. Pigo**  
 Title **Asst. Div. Engineer**