



Petroleum Engineer

(SUBMIT IN TRIPLICATE) HUBBS

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **HM 015068**Unit **P**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
Change in Well Status X	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 2, 1962

Williams Federal

Well No. 2 is located 990 ft. from ~~DM~~ [S] line and 330 ft. from [E] line of sec. 10SE/4 Section 10
(1/4 Sec. and Sec. No.)13 S
(Twp.)31 E
(Range)NMPM
(Meridian)Caprock Queen
(Field)Chaves
(County or Subdivision)New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 4133.8 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well temporary shut down.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John L. Harlan

Address Box 355

Monahans, Texas

By

Title Petroleum Engineer