

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well  gas well  other

2. NAME OF OPERATOR  
SHELL OIL COMPANY

3. ADDRESS OF OPERATOR  
P. O. Box 1509, Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FNL, 1980' FEL  
AT TOP PROD. INTERVAL: SAME  
AT TOTAL DEPTH: SAME

5. LEASE  
NM-073394-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Corder Federal

9. WELL NO.  
3

10. FIELD OR WILDCAT NAME  
Cato San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 5, T-9-S, R-30-E

12. COUNTY OR PARISH  
Chaves

13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4108-9 GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

|                          |                                     |                       |                          |
|--------------------------|-------------------------------------|-----------------------|--------------------------|
| REQUEST FOR APPROVAL TO: |                                     | SUBSEQUENT REPORT OF: |                          |
| TEST WATER SHUT-OFF      | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| FRACTURE TREAT           | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE         | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| REPAIR WELL              | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| PULL OR ALTER CASING     | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| MULTIPLE COMPLETE        | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| CHANGE ZONES             | <input type="checkbox"/>            |                       | <input type="checkbox"/> |
| ABANDON* (other)         | <input checked="" type="checkbox"/> |                       | <input type="checkbox"/> |

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

JUN - 9 1978

U. S. G. S.  
ARTESIA, OFFICE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Pull and lay down rods and pump.
2. Displace casing w/mud-laden fluid.
3. Spot 100' cement plug (14 sx) @ 3266'+.
4. Spot 100' cement plug (14 sx) @ 910'.
5. Spot 100' cement plug (14 sx) @ Surface.
6. Set concrete steel identification marker 4' above ground level.

RECEIVED  
FEB 10 1978  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct. G. W. Tullos  
SIGNED G. W. Tullos TITLE Senior Production Eng. DATE 2-9-78

APPROVED BY Albert R. Hall (This space for Federal or State office use) ACTING DISTRICT ENGINEER DATE JUN 06 1978  
CONDITIONS OF APPROVAL, IF ANY:

