

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
		7. Unit Agreement Name
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		8. Farm or Lease Name
2. Name of Operator Gulf Oil Corporation		9. Well No. 3
3. Address of Operator Box 670, Hobbs, New Mexico 88240		10. Field and Pool, or Wildcat Saunders Perno Penn.
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 34 , TOWNSHIP 14-S , RANGE 33-E , N.M.P.M.		
15. Elevation (Show whether DF, RT, GR, etc.) 4192' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> Plugged and abandoned.	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9925' TD, 9919' FB.

Pulled 2-7/8" tubing. Ran gauge ring in 7" casing to 9700'. Ran BP and set at 9702'. Circulated hole with mud. Cut and recovered 7" casing from 4794'. Spotted 30 sack, 100', cement plug from 4844' to 4744', across 7" stub at 4794'. Spotted 40 sack, 100', cement plug from 4300' to 4200', across 9-5/8" shoe at 4249'. Cut and recovered 9-5/8" casing from 800'. Spotted 55 sack, 100', cement plug from 850' to 750', across 9-5/8" stub at 800'. Spotted 75 sack, 100', cement plug from 347' to 247', across 13-3/8" shoe at 297'. Spotted 40 sack cement plug from 50' to surface. Installed dry hole marker. Plugged and abandoned February 5, 1971. (Will advise when location is ready for inspection).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
ORIGINAL SIGNED BY C. D. BORLAND	TITLE Area Production Manager	DATE February 5, 1971
SIGNED <i>Nathan E. Clegg</i>	TITLE OIL & GAS INSPECTOR	DATE JAN 19 1972
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 1 1971

OIL CONSERVATION COMM.
WASH. D. C.