

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator <u>Petroleum Corporation of Texas</u>		8. Farm or Lease Name <u>State A</u>	
3. Address of Operator <u>c/o Hobbs Pipe & Supply Co. P O Box 2010 Hobbs, N Mex.</u>		9. Well No. <u>5</u>	
4. Location of Well UNIT LETTER <u>H</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>14 S</u> RANGE <u>33 E</u> NMPM.		10. Field and Pool, or Wildcat <u>Saunders (Permo-Penn)</u>	
15. Elevation (Show whether DF, RT, GR, etc.) <u>4207' D.F.</u>		12. County <u>Lea</u>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 35 sx. cement plug at 9670'.
2. Spotted a 25 sx. cement plug at 5 1/2" casing stub at 4580'.
3. Spotted a 25 sx. cement plug at 8 5/8" casing shoe at 4200'.
4. Spotted a 10 sx. cement plug at surface with marker.
5. Hole was loaded with mud laden fluids.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Hehmedin TITLE Agent DATE March 12, 1970

APPROVED BY John W. Ramsey TITLE Geologist DATE MAY 5 1971

CONDITIONS OF APPROVAL, IF ANY: