

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Tri-Service Drilling Company		Address P. O. Box 1785, Midland, Texas			
Lease Mary F. Hyatt	Well No. 1	Unit B	Section 10	Township 13-S	Range 37-E
Date Work Performed 11-12-59	Pool Wildcat	County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☒ Casing Test and Cement Job ☐ Other (Explain):
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Ran and cemented:

4658' 9-8/8" J-55 ST&C Seamless Casing (1250' 40# - 3408' 36#)

With:

300 sacks 4% Gel and 100 sacks Reg. Neat.

Results:

Plug down 11-12-59 1 A. M.

Ran temperature survey at 9:30 A. M. Top of cement at 3637'.

Pressured up on casing for 30 min. with 1000# at 1 P. M. 11-13-59. Held okay.

Witnessed by W. S. Dearing	Position Tool Pusher	Company Tri-Service Drilling Company
--------------------------------------	--------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>John W. Runyan</i>	Name R. S. Bond
Title CONTACT REPRESENTATIVE	Position Contact Representative
Date NOV 18 1959	Company Tri-Service Drilling Company