

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS	<input checked="" type="checkbox"/>	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input type="checkbox"/>	REPORT ON REPAIRING WELL	<input type="checkbox"/>
REPORT ON RESULT OF PLUGGING WELL	<input type="checkbox"/>	REPORT ON RECOMPLETION OPERATION	<input type="checkbox"/>	REPORT ON (Other)	<input type="checkbox"/>

July 8, 1953

(Date)

Seminole, Texas

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Amerada Petroleum Corporation

(Company or Operator)

L. W. Ward

(Lease)

Rowan Drilling Company

(Contractor)

Well No 2 in the NE 1/4 SE 1/4 of Sec 11

T 13-S, R 36-E, NMPM, Brecon Silure Devonian Pool, Lea County.

The Dates of this work were as follows: July 7, 1953

Notice of intention to do the work (~~was~~) submitted on Form C-102 on _____, 19____, (Cross out incorrect words)

and approval of the proposed plan (~~was~~) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

New well - Spudded 17-1/2" hole at 8 a.m. 7-7-53.

Witnessed by C. L. Thurman Amerada Petroleum Corporation Farm Boss
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

Ray Garbrough
(Name)
Oil & Gas Inspector
(Title)

JUL 9 1953

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name W. H. Dunlap W. H. Dunlap

Position Dist. Supt.

Representing Amerada Petroleum Corporation

Address Drawer 809 Seminole, Texas