

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS	<input checked="" type="checkbox"/>	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input type="checkbox"/>	REPORT ON REPAIRING WELL	<input type="checkbox"/>
REPORT ON RESULT OF PLUGGING WELL	<input type="checkbox"/>	REPORT ON RECOMPLETION OPERATION	<input type="checkbox"/>	REPORT ON (Other)	<input type="checkbox"/>

December 20, 1952

(Date)

Monument, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Amerada Petroleum Corporation

(Company or Operator)

State # "H"

(Lease)

McVay & Stafford Drig. Co.

(Contractor)

Well No. 1 in the SW 1/4 NW 1/4 of Sec. 35

T. 14-S, R. 33-E, NMPM., Saunders Pool, Lea County.

The Dates of this work were as follows: December 19, 1952

Notice of intention to do the work (was not) submitted on Form C-102 on, 19, (Cross out incorrect words)

and approval of the proposed plan (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Spudded 17-1/2" hole @ 12:01 AM, 12/19/52

Witnessed by A. J. Troop Amerada Petroleum Corporation Farm Boss -
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

(Signature)
(Name)

(Title)

(Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name (Signature)

Position Assistant District Superintendent

Representing Amerada Petroleum Corporation

Address Drawer D, Monument, New Mexico