

FIELD REPORT NO.: 06109 D

CAPACITY: 4700#

INSTRUMENT NO.: J-1343

NUMBER OF REPORTS: 5-




CHART INDICATES TEST SYSTEM PLUGGING
DURING THE TEST.

