

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Union Texas Petroleum Corporation		5. State Oil & Gas Lease No.
3. Address of Operator 4000 N. Big Spring, Suite 500, Midland, TX 79705		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>H</u> <u>2210</u> FEET FROM THE <u>N</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>15S</u> RANGE <u>37E</u> NMPM.		8. Farm or Lease Name State <u>-A-</u>
		9. Well No. <u>2</u>
		10. Field and Pool, or Wildcat <u>Emancipation Monument</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3604' GL</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	Oil Spill <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

A back pressure valve at the A-2 tank battery failed causing a tank to overflow; spilling approximately 15 BO. The spill was confined to the caliche locatin except for a small area of grass that was sprayed due to wind. All standing oil was picked up and the rest covered.

FOR RECORD ONLY

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bruce White TITLE Reg Permit Coord DATE 3/7/86

APPROVED BY _____ TITLE _____ DATE MAR 11 1986
CONDITIONS OF APPROVAL, IF ANY: