ROSE DAVES #1

7-16-49 DST #1. From 6497 to 6525', 38 mins. test with 4½" Full Hole Drill Pipe, 2 Howco Packers set at 6489' & 6497'. Perforations 6497' to 6519' w/ 5/8" bottom and 1" top chokes. Open tool at 11:52AM w/ fair blow of air that decreased and died in 17 minutes. Hole was taking mud. Closed tool at 12:30PM for 1/4 hour BUP. Pulled out of hole and recovered 30' Drlg. mud No water, oil or gas. Howco Hydro In 3150#, Out 3100#. Flow Press 950#, 1/4 hour BUP 2000#.
Amerada's Hydro In 3030#, Out 3010#, Flor Press. 0# to 55#, 1/4 Hr. BUP 1910#

8-12-49 DST #2. From 9130' to 9214'. Testing with 4½" Full Hole Drill Pipe and 2 Howco Packers set at 9122' & 9130', Perf. 9199' to 9211' w/ 5/8" bottom and 1" top chokes. Opened tool at 6:40AM with light blow of air for 5 minutes and packer failed to hold. Pulled out of hole and recovered 1581' of Drlg. mud with no shows of oil or gas. Howco Hydro In 4500#, Out 4500#, Min. Flow Press 400# Amerada's Hydro In 4450#, Out 4400#, Min. Flow Press 85#. No Build-up Press.

9-13-49 DST #3. From 9099' to 9214', testing with 4½" OD Full Hole Drill Pipe with 2 Howco 9" OD Packers set at 9091' & 9099'. Perf. 9199' to 9211' with 5/8" bottom & 1" top chokes. Open tool 4 times & packers failed to hold immediately. Tool opened at 4:15PM, 4:25PM, 4:30PM, 4:40PM. Closed tool and pulled out of hole. Recovered 1767' of Drlg. mud, now shows of oil or gas. Hydro In 4500#, Out 4450#, Min. Flow 1100#, No Max. Amerada's Hydro In 0#, Out 4410#, Min Flow Press. 655#, No Max. No Build-up Pressure.