



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. 029405 b  
Unit Lease

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Perforate & Treat

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Wm. Mitchell B January 31, 1961

Well No. 38 is located 660 ft. from N line and 1980 ft. from E line of sec. 18

SE/4 SW/4 Sec. 18 17-S 32-E NMPM  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Maljamar Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3964 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Before: TD 4160', PB 4115', DF 11', Elev. 3964'. Pay Grayburg - San Andres 3759-4110'. Csg. Pt. 5 1/2" at 4159'. Perfs. 3759-66', 4089-93', 4097-4110'. Pumped 1.5 BO, 8 BW, in 48 hours with TSTM MCFGPD. Daily oil rate 0.75 Bbls. Daily Allowable 4 BO. Work Done: Set CIBP at 3766'. Perforated 3660-69', 3674-81', 3699-3721', 3738-50' with 4 JSPF. Treated 3660-3764' with 50,000 gals. lease crude, 50,000 lbs. sand, 1650 lbs. Adomite. AFTER: TD 4160', PB 3766'. Pay Grayburg 3660-3766. Perfs. 3660-69', 3674-81', 3699-3721', 3738-50', 3759-66'. Pumped 9 BO, no water, in 24 hours with 10.1 MCFGPD, GOR 1122. Daily allowable 9 BO. Workover started 11-4-60, completed 11-14-60, tested 1-30-61.

USGS-3 WAM File

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Rowley Building

Artesia, New Mexico

By \_\_\_\_\_

Title District Superintendent