

SANTA FE NEW MEXICO

Form No. 103
Revised 10/78

DATE
FILE
NAME OF WELL
OPERATOR

State New Mexico
V-135

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-DRILL OR TO PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL FROM C-101 FOR SUCH PROPOSALS.

OIL WELL GAS WELL OTHER

NAME OF OPERATOR
MWJ PRODUCING COMPANY

ADDRESS OF OPERATOR
1804 First National Bank Bldg. Midland, Texas 79701

LOCATION OF WELL
UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East LINE. SECTION 9 TOWNSHIP 15S RANGE 33E

7. Unit Agreement Name

8. Field or Lease Name
Saunders 9 State

9. Well No.
1

10. Field and Prod. or Wellcat
Saunders Upper Permian

12. County
Lea

15. Elevation (Show whether DF, RT, CR, etc.)
4198.1' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
<input type="checkbox"/> REFORM REMEDIAL WORK	<input type="checkbox"/> PLUG AND ABANDON	<input type="checkbox"/> REMEDIAL WORK	<input type="checkbox"/> ALTERING CASING
<input type="checkbox"/> IMPROPERLY ABANDON	<input type="checkbox"/> CHANGE PLANS	<input checked="" type="checkbox"/> COMMENCE DRILLING OPER.	<input type="checkbox"/> PLUG AND ABANDONMENT
<input type="checkbox"/> RE-OR ALTER CASING	<input type="checkbox"/>	<input checked="" type="checkbox"/> CASING TEST AND ELEMENT JOB	<input type="checkbox"/>
<input type="checkbox"/> OTHER	<input type="checkbox"/>	<input type="checkbox"/> OTHER	<input type="checkbox"/>

Describe Proceeds or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/7/82: MI Tri-Service Drlg Rig #8.

6/10/82: Spudded @ 10: AM 6/8/82 & drld to 382'. Ran 10 jts 13-3/8" 48# csg & set @ 382'. Cmt'd w/400 sx Class "C" w/2% CaCl. PD @ 10: PM 6/8/82. Circ'd approx 20 sx. Test to 1000 psi for 15 min, OK.

6/17/82 Drld to 4237'. RU & ran 104 jts 24# & 32# 8-5/8" csg & set @ 4237'. Cmt'd w/1300 sx Halliburton Lite w/15# salt & 1/4# floccel followed by 200 sx Class "C" w/2% CaCl. PD @ 1:15 AM 6/18/82. Ran temp survey & found top of cement @ 800'. PI csg to 600 psi for 30 min, OK. Drld 150' cement, float collar & shoe. Drlg ahead.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Pat Bishop

TITLE Agent DATE 6/18/82

OPTIONAL COPY BY
JERRY GANTON
DISTRICT SUPERVISOR

DATE JUN 23 1982

CONDITIONS OF APPROVAL, IF ANY