

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 0554244

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Edith Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 23-185-32 E

12. COUNTY OR PARISH

13. STATE

Lea

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER Dry

2. NAME OF OPERATOR

JOHN H. HILL

3. ADDRESS OF OPERATOR

7607 Brookhollow Cove Austin, Texas 78752

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

2310' from South line, 990' from East line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3782.6 Gr, 3793 KB

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING/OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

Reached TD 4281' 1-10-75. DST in Queen 3950'-4030', and Penrose 4210'-4281'  
recovered no hydrocarbons. Pumped 35 sk cement plug 3950'-3850', 40 sk plug  
2700'-2600', 45 sk plug 1250'-1150', 45 sk plug 400'-300', and 10 sk plug at  
surface w/dry hole marker. Left 9.6 # mud between plugs. Plugged and abandoned  
1-12-75. (Verbal approval given by Mr. Brown 1-10-75).

18. I hereby certify that the foregoing is true and correct

SIGNED

*John H. Hill*

TITLE

Superintendent

DATE 1-21-75

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

APPROVED

NOV 26 1975

ARTHUR R. BROWN  
DISTRICT ENGINEER