Form 3160-5 (June 1990)

## JNITED STATES DEPARTMENT OF THE INTERIOR

N.M 🖳	៕ Co⊓
P	1980
Hobbs	NM 8824


FORM APPROVED Budget Bureau No. 1004-0135

RURFALLOF	LAND MANAGEMENT	
DOREAC OF	LAND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS		LC-065710-A
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT—" for such proposals		NA
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well		
Oil Gas Well Other Injector		8. Well Name and No. Lusk West
2. Name of Operator		(Delaware) Unit #009
Pioneer Natural Resources USA, Inc.		9. API Well No.
3. Address and Telephone No.		30-025-30490
P. O. Box 3178, Midland, TX 79702		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Lusk Delaware, West
330' FSL & 1980' FEL, Sec. 20, T19S, R32E		11. County or Parish, State
		Lea County, NM
CHECK APPROPRIATE BOY	(s) TO INDICATE NATURE OF NOTICE REPORT	7 00 00
	s) TO INDICATE NATURE OF NOTICE, REPOR	I, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
[ <del>V</del> ]	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
. Describe Proposed or Completed Operations (Clearly state at	pertinent details and give positions down 1 1	,

13. s, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well was permitted as Lusk Deep Unit "A" #20

See Attached Well Chronology Report and Pressure Chart



4. I hereby certify that the foregoing is true and correct Signed	Title Operations Engineer	Date 10/21/97
(This space for Federal or State office use)		
Approved by	Title	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BORNETT GULLDEN SON

1997 007 31 P 2: 32

## WELL CHRONOLOGY RL. ORT

WELL NAME: LUSK DEEP UNIT "A" #20

OPERATOR: PIONEER NATURAL RESOURCES COMPANY

LUSK WEST (DELAWARE)

COUNTY & STATE : LEA

NM

UNIT I, 660' FEL & 2310' FSL, SEC. 20, T-19-S. LOCATION:

FORMATION: **BRUSHY CANYON** 

**REPORT DATE: 9/23/97** 

DAILY DETAILS: FIRST REPORT.

MI RU WSU. POOH & LAY DOWN RODS & PUMP. RU BOP. SION.

REPORT DATE: 9/24/97

DAILY DETAILS: LOWER TBG TO APPROXIMATELY 7138' & TAG BOTTOM. RU TUBESCOPE. SCOPE TBG OUT OF

HOLE. MOVE IN 102 JTS 2 7/8" TBG FROM LUSK DEEP #14A. TIH W/TBG. SCOPE TBG OUT OF HOLE. RU PRO-LOG. RIH W/5 1/2" CIBP. GOT ON DEPTH W/COLLARS. SET CIBP AT 7000'. MADE 2 BAILER RUNS. SPOTTING 35' OF CEMENT ON CIBP. SIW & SDFN.

PIPE RECOVERY: LUSK DEEP 20A

197 JTS YELLOW BAND 10 JTS BLUE BAND 14 JTS GREEN BAND 1 JT RED BAND

LUSK DEEP 14A 82 JTS YELLOW BAND 5 JTS BLUE BAND 0 JTS GREEN BAND 2 JTS RED BAND

**REPORT DATE: 9/25/97** 

DAILY DETAILS: NO REPORT. WILL RECEIVE IPC TBG THURSDAY AM & WILL RESUME OPERATIONS.

**REPORT DATE: 9/26/97** 

DAILY DETAILS: MI & RACK 2 3/8" IPC TBG. PU 5 1/2" ARROW SET I-XS PKR. TIH TO 6408.73 KB. RU KILL TRUCK. PUMP 120 BLS PKR FLUID (PETROLITE CRW 132). SET PKR. PUMP 10 MORE BLS. CSG NOT QUITE FULL. REMOVE BOP. FLANGE UP. INSTALL MASTER VALVE & FLOW CHECK VALVE.

SDFN.

202 - JTS 2 3/8" 4.7# J-55 IPC TBG

6385.58 1.40

5.75

1 - T-2 ON/OFF TOOL SS 1 - 2 3/8" "F" TYPE SEAL NIPPLE SS 1 - ARROW SET I-XS 5 1/2" X 2 3/8" NICKLE PLATED IPC (PKR SET W/5000# COMPRESSION)

6392.73 16.00 KB

6408.73 KB

**REPORT DATE: 9/27/97** 

DAILY DETAILS: RU KILL TRUCK. LOAD CSG WITH 18 BL PKR FLUID. HAD TROUBLE TESTING CSG. FOUND LEAK

ON TRUCK, REPAIRED. RAN CHART TEST TO 500# FOR 25 MINUTES, HELD. RDMO.

FINAL REPORT

