

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator H. L. BROWN, JR.	8. Farm or Lease Name State "B" 18
3. Address of Operator 309 Midland Tower, Midland, Texas 79701	9. Well No. #1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Scharb Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3,936' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER _____	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted a 30 sx plug to cover existing perforations, 9600'.
2. Cut & Pulled 4-1/2" casing from 7,250'.
3. Spotted a 35 sx cement plug @ 4-1/2" casing stub.
4. Spotted a 50 sx plug @ 4,070', in & out of 8-5/8" casing.
5. Cut & pulled 8-5/8" casing from, 1,270'.
6. Spotted a 50 sx plug @ 1,000'.
7. Spotted a 50 sx plug @ 450'.
8. Placed a 10 sx plug @ surface & erected a 4" regulation marker.
9. Well was plugged & abandoned on 8/7/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stanley Siskin TITLE Agent DATE 8/21/73

APPROVED BY Nathan E. Olegg TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: