

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33429
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-155-1
7. Lease Name or Unit Agreement Name	VACUUM GLORIETA WEST UNIT
8. Well No.	89
9. Pool Name or Wildcat	VACUUM GLORIETA

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter _____ : _____ 2000 Feet From The SOUTH Line and 1070 Feet From The EAST Line Section 36 Township 17-S Range 34-E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3988' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	OTHER:	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input checked="" type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPERATION	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER:	<input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-02-97: MIRU. RU FLOWLINE & CIRC EQPT. RACK & COLLAR & STRAP DP. TAG CIBP @ 5856' SLM. TEST CSG TO 1200 PSI. HELD FOR 15 MIN. TIH W/WHIPSTOCK @ SET @ 41 DEG. RAN GYRO SURVEY
 12-03-97: TIH W/MILL & MILL FR 5856-5867'. TIH W/#1 BHA. SLIDE DRLG FR 5867-5869'.
 12-04-97: SLIDE FR 5869-5964.
 12-05-97: SLIDE FR 5964-6270
 12-06-97: SLIDE FR 6270-6676.
 12-07-97: SLIDE FR 6676-7265.
 12-08-97: SLIDE FR 7265-7283'. TIH W/LOKSET & SET @ 3987'. TEST TO 1200 PSI. TURN OVER TO PRODUCTION.
 12-12-97: PSA 5756'. PSI CSG TO 500-OK. SWAB 1ST FL @ SURF. END FL @ 2000'.
 12-13-97: START FL @ 1600'. END FL @ 3000'. RDMO.
 12-19-97: PUMPED UP @ 10 AM. ON TEST.
 12-20 THRU 12-22-97: PUMPING & TESTING.
 1-15-98: SWAB 1ST FL @ 1400'. END FL @ 2800'. REL PKR.
 1-17 THRU 1-31-98: PUMPING & TESTING.
 1-31-98: ON 24 HR OPT. PUMPED 46 BO, 1322 BW, & 17 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 3/9/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

