24 25 42 115 25 25 44 15 2	~		`	٠.,	.	
NO. OF COMES PECCIVED					Form C-103	·
DISTRIBUTION					Supersedes Old C-102 and C-103	
SANTA FE	NEW MEX	ICO OIL CONS	ERVATION COMMISSION		Effective 1-1-	
FILE	1					
U.S.G.S.					5a. Indicate Type	of Leano
LAND OFFICE					State	Fee X
	 -		• •		5. State Oil & G.	
OPERATOR					3. Oldle On a Ca	a mease No.
					~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	"I "I " " Service on more many or a result of the
SU	MDRY NOTICES AND P	EPORTS ON	WELLS			
LOO HOT USE THIS FORCE FOR	107 HS 3 477, 01 PURKELSON PE (1001) *** THERMAN POT ZOLEKSTE	TURNES ON PLUG E U CHIOLFOR SUS	ACK TO A DIFFERENT RESERVOIR. IL PECPUSALS. I	•	MIIIII	
1.					7. Unit Agreener	t Nume
OTL GAS WELL WELL	orner- Water	Supply Mal'	1		ĺ	
z. Name of Operator	Water	ouppry wer.	L		6, Farm or Lease	Tions
Gulf Oil Corporation					B.V. Culp (NCT-A)	
1. A ldress of Operator					9. Well No.	
Box 670 Hobbs, NM 88240					8	
4. Lecution of Well					10. Field and Pool, or Wildest	
UNIT LETTER F . 2310 FEET FROM THE NORTH LINE AND 2239 FEET FROM					Eumont	
UNIT LETTER	FELT FROM TO	1E	LINE ANDF	CET FROM	77777777	TTTTTTTT
Work	: 10	10	C 27 F			
THE West	SECTION 19 TOW	NSHIP	-D RANGE 3/-E	NMPM.		
ara menare e e e a a caración de la comoción de la						
	15. Elevetica		DF, RT, GR, etc.)		12. County	HHHH
		3689¹ GI			Lea	XIIIIIII
16.	ale Annanai na Day T	. I. J N		~	***	-47/77/7/7/7/
		o indicate N	ature of Notice, Report			
NOTICE O	F INTENTION TO:		SUBSE	QUENT	REPORT OF:	
		1				
PERFORM REMEDIAL WORK	PLUG AN	D ABANDON	REMEDIAL WORK	X	ALTERI	HG CASING
TEMPERATILY ABANDON			COMMENCE DRILLING OPHS.	Π	PI IIG A	ND ABANDONMENT
PULL OR ALTER CASING	CHANGE		CASING TEST AND CEMENT JOB	闩		T_
Poce on Action charms	endi4:			لـــا		
		[]	OTHER			L
отнея						
7. Describe Proposed of Complete	od Operations (Clearly, state o	Il partinent data	ile and also partingst datas i	nalvilium e	atimutad data at a	****
work) SEE RULE 1103.	A Operations (Citari) state a	it penthent acta	its, and give pertinent dates, i	nemaing e	stimuited date of s	tarting any proposei
5790 PB						
		•	•			
Pulled 5½" tubing.	Found casing leak	at 930 and	1450'. Set RBP at	2031'	caped with	10
sacks sand. Set cem						
250 sacks class C w					4	
with 2750 sacks lit	e cement containing	g ½# floce]	le, 12½# gilsonite,	30# sa	alt with 2%	CaCL
and 350 sacks clas	s C with 2% CACL.	Orilled cer	ment retainer and co	ement t	to 1014'.	
Tested upper leak w						th 2. ½"
JHPF. Set cement r						
		-				•
annulus with 230 sa						ezed
perfs with 200# - 0						
26#, 26.40# and 2 9#						
.5% CFR-2 and 2% sa	lt. Cement circula	ted. Test	ed casing with 300#	for 30) minutes -	OK.
Ran 4 ½" tubing and						
• • • • • • • • • • • • • • • • • • •			- 11 3			
3. I hereby certify that the informa	this phone is true and counts	te to the best of	my knowledge and belief			
, , nejedy certal, time the informa			my montespe and other			
July hall	4					
ento / 1 /// Call	ecells	TITLE_ Are	ea Engineer		DAYE Jul	<u>у 7, 1977</u>
22-140-24-24-24-24-24-24-24-24-24-24-24-24-24-						
	Orig. Signed by		S. English		1123	1000
	John Runyer				- 47 8	
	gramman was well by to				the second secon	and the second s

THE THAT

CIL CONSERVATION COMM.