

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-05800

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

Amerada Hess Corporation

3. Address of Operator

Drawer D, Monument, New Mexico 88265

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line

Section 33 Township 19S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3569' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-6 thru 8-10-90

MIRU Clarke Oil Well Svc. pulling unit & installed BOP. Ran 5-7/8" bit to fish at 3560' & TOH. Ran 5-1/2" Klustrite Shoe & tagged up at 2176'. TOH w/tools. Ran 5-7/8" impression block & set down w/4000# at 2176'. TOH & found 6-5/8" csg. had collapsed on two sides. Ran 5-7/8" swage & swaged out 6-5/8" csg. at 2176'. Ran 5-1/2" shoe to 2720', could not get any deeper. TOH w/tools. Ran 5-7/8" swage & swaged out 6-5/8" csg. fr. 2720' to 2825'. Ran a three arm caliper & checked bottom at 3540'. Logged 6-5/8" csg. fr. 3530' to 1960'. Suspect csg. parted fr. 2710' to 2720'. Ran 5-1/2" csg. swage to 2825' & TOH. Ran 2-7/8" x 6' mule shoe sub & worked down to 2825'. TOH laying down tbgs. & tools. Removed BOP & installed well head. RDPU & cleaned location. Closed well in for evaluation.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr.

TITLE Supv. Adm. Svc.

DATE 8-31-90

TYPE OR PRINT NAME R. L. Wheeler, Jr.

TELEPHONE NO. 393-2144

(This space for State Use)

APPROVED BY Paul Rantz TITLE Geologist DATE 8-31-90

CONDITIONS OF APPROVAL, IF ANY: