

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

N/A

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

N/A

7. Lease Name or Unit Agreement Name

LPG  
RAW PRODUCT STORAGE WELL

8. Well No.

2

9. Pool name or Wildcat

N/A

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☐

OTHER

LPG STORAGE

2. Name of Operator

WARREN PETROLEUM COMPANY Chevron USA INC

3. Address of Operator

P. O. BOX 67, MONUMENT, NEW MEXICO 88265

4. Well Location

Unit Letter M : 1020 Feet From The SOUTH Line and 1220 Feet From The WEST Line

Section 36 Township 19S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

N/A

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. BRINE PRESSURE TEST (6-5-01 - 6-10-91)

2. REMOVED EXISTING WELL HEAD AND TUBING

3. RAN LOGS

SONAR SURVEY (6-20-91 - 6-21-91)

DIRECTIONAL SURVEY (6-26-91)

CALIPER SURVEY AND ACOUSTIC CEMENT BOND / VDL LOG (6-22-91)

DENSITY SURVEY (6-26-91)

VERTILOG (6-30-91)

4. SET 7" CASING LINER FROM SURFACE TO 1136' DUE TO INCOMPLETE CEMENT BOND AND PITTING

5. RAN MECHANICAL INTEGRITY TEST (7-10-91 - 7-17-91)

6. REPLACED WELL HEAD AND TUBING (5" - 1465')

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. L. Coarsey TITLE PLANT MANAGER DATE 09-19-91

TYPE OR PRINT NAME C. L. COARSEY TELEPHONE NO. 393-2823

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: