

Form 9-331a
(Nov. 1936)
Indian Agency

Allottee

Lease No.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

U. S. Land Office Lad Cruces, N. M.
Lease or permit No. 031621-B

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO RE-DRILL ACIDIZE	☒	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

P.P.Co.
Hobbs

Well No. Two is located 1980 ft. from N line and 660 ft. from W line of sec. 18
SW/4, Sec. 18 20-S 37-E N. M. P. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Monument
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3573 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total Depth 3865. It is proposed to treat pay formations from 3767 to 3865 with 4000 gallons acid solution.

Second treatment.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum
Address Box 1390, Midland, Texas

By /s/ Earl Griffin
Title District Superintendent

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPLICATE)

SUMMARY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE	1
NOTICE OF INTENTION TO TEST	2
NOTICE OF INTENTION TO RE-DRILL	3
NOTICE OF INTENTION TO PULL OR ALTER CASING	4
NOTICE OF INTENTION TO ABANDON WELL	5
NOTICE OF INTENTION TO ACIDIZE	6
REPAIR WELL	7
SUPPLEMENTARY WELL	8
SUBSEQUENT REPORT OF ABANDONMENT	9
SUBSEQUENT REPORT OF REPAIRS OR RE-DRILLING	10
SUBSEQUENT REPORT OF ALTERING CASING	11
SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	12
SUBSEQUENT REPORT OF WATER SAMPLING	13

(INDICATE ABOVE BY CHECK MARK NATURE, F. R. 100-1000, 1000-1000, 1000-1000)

F. R. 100-1000

Well No. 100-1000 is located 100 ft. from 100-1000

See

100-1000

100-1000

100-1000

100-1000

100-1000

100-1000