

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Los Cruces**
Lease No. **664501**
Unit **Murray**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 31, 1947

Well No. **1** is located **1980** ft. from **N** line and **1980** ft. from **E** line of sec. **9**
33/4 co. **9** **225** **325** **N.E. 1/4**
 (Field) (Twp.) (Range) (Meridian)
Liberty **Los** **New Mexico**
 (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3814** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-5/8" - 23 1/2 lb. seamless casing set at 1121' and cemented with 50 sacks of Halliburton on December 30, 1947. Will set 72 lb. casing, drill plug and bail hole to test for water shut-off on January 2, 1948.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Culbertson & Irwin, Inc.**

Address **Box 1071, Bigland, Texas**

By _____

Title **President**