

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CORP. (Other Instructions on re-
entry side)
HOBBS, NEW MEXICO 88202

CONTRACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
BHM Roswell District
Modified Form No.
NM60-3160-4

LEASE DESIGNATION AND SERIAL NO.

NM-77058

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> <u>Re-entry</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Strata Production Company		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR P. O. Box 1030, Roswell, New Mexico 88202-1030		8. FARM OR LEASE NAME Cercion Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 660' FWL		9. WELL NO. #7	
10. FIELD AND POOL, OR WILDCAT Livingston Ridge Delaware East		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 22-22S-32E	
14. PERMIT NO. 30-025-08110	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3678' GR	12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

Re-entry


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

02/18/93: MI and RU Grace Drilling Rig #405. Drilled to 3744'. Drill pipe stuck at 3744'. Work free. Drilled to 4248'. Drill pipe stuck at 4248'. Fishing drill pipe.

02/20/93: Run free point at 4302'. Fishing drill pipe.

02/21/93: TOH and LDDP at 4302'. Prep to set cement plugs.



CARLSBAD
AREA
MAR 5 11 40 AM '93

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED Carol J. Garcia

TITLE Production Supervisor

DATE 3/4/93

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side