

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. BOX 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-34160

5. Indicate Type of Lease

☐ STATE

☒ FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Joe Camel

8. Well No.

1

9. Pool name or Wildcat

House Drinkard/House Blinebry South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

☒ OIL WELL

☐ GAS WELL

☐ OTHER

2. Name of Operator

MW Petroleum Corporation

3. Address of Operator

2000 POST OAK BLVD., SUITE 100, HOUSTON, TX 77056-4400

4. Well Location

Unit Letter K : 1980' Feet From The South Line and 1980' Feet From The West Line
Section 13 Township 20 South Range 38 East NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3569' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

☐ Perform Remedial Work

☐ Plug and Abandon

☐ Temporarily Abandon

☐ Change Plans

☐ Pull or Alter Casing

☐ Other

☐ Remedial Work

☐ Altering Casing

☒ Commence Drilling Operations

☐ Plug and Abandonment

☒ Casing Test and Cement Job

☐ Other

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

11/13/97 MIRU. Spud @ 6:15 pm

11/15/97 Drld 11" hole to 1624'. Ran 36 jts of 8 5/8", 24#, J-55, ST&C. Cmt'd w/475 sks PBCZ.
Circ. 97 Sks to Pit.

11/27/97 Drld 7 7/8" hole to 7200'. Ran 189 jts of 5 1/2", 17#, K-55, LT&C. Cmt'd w/1700 sks,
1100 sks lead P-Hound Lite, 600 sks tail 50/50 poz+2% Gel+2.4# Salt+1/4# Flocele.
Circ. 175 Sks to Pit. Plug down. Held OK. Tested 3000 PSI. OK.

11/28/97 Released Rig @ 5:00 am

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Sr. Engineering Tech

DATE 1/14/98

TYPE OR PRINT NAME

Cecelia Glud

TELEPHONE NO. 713/296-7129

(This space for State Use)

APPROVED BY

TITLE

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

DATE

1/28/99

CONDITIONS OF APPROVAL, IF ANY:

