

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Dalport Oil Corporation, 930 Fidelity Union Life Bldg. Dallas, Texas
(Address)

LEASE Otis L. Jones "B" WELL NO. 1 UNIT J S 34 T 22-S R 36-E
DATE WORK PERFORMED 2-18-57 POOL South Eunice

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other Completion

Detailed account of work done, nature and quantity of materials used and results obtained.

Perforated from 3642 to 3652 and 3680 to 3730. Spotted 500 gal. mud acid on perforation.
Fracced with 7000 gals, using 1 1/4 lbs of sand per gal; dropped 100 Western perforation
sealing balls, and completed treatment with 3000 gallons frac. After recovering
load oil well flowed 1 1/4 B. O. in 3 hours.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name

Name

Title

Position

Date

Company

Dalport Oil Corporation