

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office **Las Cruces**  
Lease No. **LC 030133 a**  
Unit **HMPU**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Meyer A-29**

**May 29**, 19 **57**

Well No. **6** is located **660** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **29**  
**1/4 Sec 29** (1/4 Sec. and Sec. No.)      **22 S 36 E** (Twp.)      **HMPU** (Meridian)  
**South Union** (Field)      **Lea** (County or Subdivision)      **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 118 fts 5 1/2" casing set at 3814' with 1106 sacks, top of cement 1325'. Plug down 5-22-57. Tested casing with 1000# before drilling plug, no pressure drop. TD 3815', DOD 3811'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**  
Address **Box 68**  
**Union, New Mexico**  
By \_\_\_\_\_  
Title **District Superintendent**