



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_  
Lease No. \_\_\_\_\_  
Unit \_\_\_\_\_

1955 OCT 27 AM 9 28

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 300 ft. from N line and 300 ft. from E line of sec. 30  
1/4 of 1/4 (1/4 Sec. and Sec. No.) 28 (Twp.) 30 (Range) N 100 W (Meridian)  
Lex (County or Subdivision) N. Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3104 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 12 1/4" hole 362', set 302' of 3 5/8" 24#, circulated cement.  
 Waited on cement 24 hrs. drilled out.  
 Drilled 7 7/8" hole 4704', set 4704' of 3 1/2" 15.5# casing, cement with  
 300 sacks, 24 hrs., tested with 1000 pressure, plugs held,  
 tested cement with 1000 pressure, cement held, drilled out.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Deville L. Marine Inc.

Address Box 900

Quince, Tex 79123

By ...

Title Agent