



Indian Agency

(SUBMIT IN TRIPLICATE)

U. S. Land Office **Las Cruces**Lease or permit No. **030174 (b)**

Allottee

Lease No.



## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, January 17th, 1940

W. H. Rhodes (b)

Well No. 1 is located 1650 ft. from [N] line and 1650 ft. from [E] line of sec. 27NE 4 Sec. 27

(1/4 Sec. and Sec. No.)

T-26-S

(Twp.)

R-37-E

(Range)

N.M.P.M.

(Meridian)

Rhodes

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 2991 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T. D. 1215' - Anhydrite.

Set &amp; cemented 1196' of 9-5/8" 36# LW Casing @ 1210' with 450 sacks. Completed cementing 3:25 AM - 1-13-40.

Drilled plug at 12:00 Noon - 1-16-40. Tested casing before and after drilling plug with 1000#. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company,Address Box 1270,Midland, Texas.By [Signature]Title District Superintendent

