Form 9-881 a (Feb. 1951) A 12 0 1963

E. G. HUBBLE

• •

(SUBMIT IN TRIPLICATE)

(ATE)

DEPARTMENT OF THE INTERIOR

D E 16-030180 (a)

SUNDRY NOTICES AND REPORTS ON WELLS

	NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF ALTERING CASINGSUBSEQUENT REPORT OF RE-DRILLING OR REPAIRSUBSEQUENT REPORT OF ABANDONMENTSUPPLEMENTARY WELL HISTORY	
--	------------------------------	--	--	--

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

C. M. Farnsworth "A"		August 12,	روم 19
Well No is located	660 ft. from S line	1663.2 and ft. from $\{W\}$ line of sec	. 18
SE/4, 3W/4, Sec. 18	T-26-S, R-37-E	NMPM	
(1/4 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)	
Jalmat - 041	Loa	New Mexico	
(Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is NYA ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cactus brilling Co. spudded 11" hole on 8-9-63. On 3-9-63, 8-5/3" OD 24# J-55 casing was set at 318' with 125 sx. cement circulated. After WOO 18 hours, tested casing with 600 PSI for 30 minutes. Test OK. Reduced hole to 7-7/8" at 318' and resumed drilling operations.

Title

Pan American Petroleum Corporation

Pan American Petroleum Corporation

Original Signed by:
V. E. STALEY

Area Superintendent